

From: Cynthia Giles-AA/DC/USEPA/US
To: Steven Chester/DC/USEPA/US@EPA
Date: 03/19/2012 06:46 PM
Subject: Fw: Range

Steve - I think it would be good for you to call Bob S to discuss what should happen on the call tomorrow re the state matter. Can't remember if you and I discussed that. Thanks for your work on this, even with the multiple challenges of working remotely.


See you tomorrow -

Cynthia

----- Forwarded by Cynthia Giles-AA/DC/USEPA/US on 03/19/2012 06:44 PM -----

From: Bob Sussman/DC/USEPA/US
To: Avi Garbow/DC/USEPA/US@EPA, Steven Chester/DC/USEPA/US@EPA, Cynthia Giles-AA/DC/USEPA/US@EPA, Scott Fulton/DC/USEPA/US@EPA
Date: 03/19/2012 06:22 PM
Subject: Range

Al sent me the enclosed materials from the state litigation, which make clear Range's demands for documents reflecting the counter-claim defendants' communications with EPA. (b) (5)



I'm scheduled to talk to Ray Walker (and perhaps Poole) about the ORD issues tomorrow afternoon. I'm hoping Steve will join, along with representatives of ORD.

Robert M. Sussman
Senior Policy Counsel to the Administrator
Office of the Administrator
US Environmental Protection Agency
(202) 564-7397

----- Forwarded by Bob Sussman/DC/USEPA/US on 03/19/2012 06:18 PM -----

From: Al Armendariz/R6/USEPA/US
To: Bob Sussman/DC/USEPA/US@EPA
Cc: Bob Perciasepe/DC/USEPA/US@EPA, Donald Maddox/DC/USEPA/US@EPA
Date: 03/18/2012 02:49 PM
Subject: phone calls

Hi Bob,

As part of your role in the immediate effort to reset the tenor, I'd like to talk to you about the attached documents. The first a document from the tx state litigation, and the second a document about activities in the marcellus.

I've sent an invitation to talk 1230 ET Monday. If that doesn't work, perhaps another time late Monday or mid-day Tuesday.

RANGE RESOURCES APPALACHIA LLC	02/14/2011	081-20238	78.85 - Inadequate, insufficient, and/or improperly installed cement	Bubbling in the annulus of the 9 5/8 x 13 3/8 casing
RANGE RESOURCES APPALACHIA LLC	02/22/2011	081-20238	78.86 - Failure to report defective, insufficient, or improperly cemented casing w/in 24 hrs or submit plan to correct w/in 30 days	02/14/11 gas bubbling in the cellar found to be in the annular space of the 9 5/8 x 13 3/8 casing. 02/16/11 Methane detected with a dept. MSA model 60 gascope.
RANGE RESOURCES APPALACHIA LLC	02/07/2012	081-20292	78.86 - Failure to report defective, insufficient, or improperly cemented casing w/in 24 hrs or submit plan to correct w/in 30 days	Defective cement 78.86: Gas found pressure and flow on 2 annuli. Both the 9 5/8 x 5 1/2 and the 13 3/8 x 9 5/8
RANGE RESOURCES APPALACHIA LLC	09/23/2011	081-20313	78.83GRNDWTR - Improper casing to protect fresh groundwater	Failure to report lost cement circulation on the surface casing. No cement return to surface.
RANGE RESOURCES APPALACHIA LLC	02/16/2011	081-20385	78.85 - Inadequate, insufficient, and/or improperly installed cement	Bubbling in the annulus of the 9 5/8 x 13 3/8 casing
RANGE RESOURCES APPALACHIA LLC	02/22/2011	081-20385	78.86 - Failure to report defective, insufficient, or improperly cemented casing w/in 24 hrs or submit plan to correct w/in 30 days	02/14/11 Gas bubbles in the cellar found to be the annulus of the 9 5/8 x 13 3/8 casing. 02/16/11 Methane was detected with a dept. MSA model 60 gascope.
RANGE RESOURCES APPALACHIA LLC	12/02/2011	081-20387	78.86 - Failure to report defective, insufficient, or improperly cemented casing w/in 24 hrs or submit plan to correct w/in 30 days	Gas found with the presence of methane in the 9 5/8 x 5 1/2 annulus. 100% methane with 105 cuft/day
RANGE RESOURCES APPALACHIA LLC	11/23/2011	081-20480	78.86 - Failure to report defective, insufficient, or improperly cemented casing w/in 24 hrs or submit plan to correct w/in 30 days	gas that was not self reported was found with the presence of methane in the 13 3/8 x 9 5/8 annulus and the 9 5/8 x 5 1/2 annulus
RANGE RESOURCES APPALACHIA LLC	11/23/2011	081-20481	78.86 - Failure to report defective, insufficient, or improperly cemented casing w/in 24 hrs or submit plan to correct w/in 30 days	gas that was not self reported was found with the presence of methane in the 13 3/8 x 9 5/8 annulus and the 9 5/8 x 5 1/2 annulus
RANGE RESOURCES APPALACHIA LLC	11/23/2011	081-20482	78.86 - Failure to report defective, insufficient, or improperly cemented casing w/in 24 hrs or submit plan to correct w/in 30 days	gas that was not self reported was found with the presence of methane in the 13 3/8 x 9 5/8 annulus and the 9 5/8 x 5 1/2 annulus
RANGE RESOURCES APPALACHIA LLC	11/23/2011	081-20483	78.86 - Failure to report defective, insufficient, or improperly cemented casing w/in 24 hrs or submit plan to correct w/in 30 days	gas that was not self reported was found with the presence of methane in the 13 3/8 x 9 5/8 annulus and the 9 5/8 x 5 1/2 annulus

RANGE RESOURCES APPALACHIA LLC	11/23/2011	081-20484	78.86 - Failure to report defective, insufficient, or improperly cemented casing w/in 24 hrs or submit plan to correct w/in 30 days	gas that was not self reported was found with the presence of methane in the 9 5/8 x 5 1/2 annulus
RANGE RESOURCES APPALACHIA LLC	11/23/2011	081-20485	78.86 - Failure to report defective, insufficient, or improperly cemented casing w/in 24 hrs or submit plan to correct w/in 30 days	gas that was not self reported was found with the presence of methane in the 13 3/8 x 9 5/8 annulus and the 9 5/8 x 5 1/2 annulus
RANGE RESOURCES APPALACHIA LLC	09/23/2011	081-20489	78.83GRNDWTR - Improper casing to protect fresh groundwater	Failure to report lost cement circulation on the surface casing. No cement return to surface.
RANGE RESOURCES APPALACHIA LLC	10/18/2011	081-20596	78.86 - Failure to report defective, insufficient, or improperly cemented casing w/in 24 hrs or submit plan to correct w/in 30 days	Bubbling between the 13 3/8 x 9 5/8 annulus. Not self reported. Could not detect methane.
RANGE RESOURCES APPALACHIA LLC	03/27/2007	125-22472	78.86 - Failure to report defective, insufficient, or improperly cemented casing w/in 24 hrs or submit plan to correct w/in 30 days	
RANGE RESOURCES APPALACHIA LLC	03/27/2007	125-22472	78.86 - Failure to report defective, insufficient, or improperly cemented casing w/in 24 hrs or submit plan to correct w/in 30 days	